

Total No. of Questions : 9]

SEAT No. :

P2549**[5153]-514**

[Total No. of Pages : 2

T.E.(Mechanical)**METROLOGY AND QUALITY CONTROL****(2012 Pattern) (Semester - I) (End Sem.)****Time : 2½ Hours]****[Max. Marks : 70****Instructions to the candidates:**

- 1) *Neat diagrams must be drawn wherever necessary.*
- 2) *All questions are compulsory. ie. (Solve Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8)*
- 3) *Assume Suitable data if necessary.*
- 4) *Use of Calculator is allowed.*
- 5) *Figures to the right side indicate full marks.*

- Q1)** a) State the methods for checking External and Internal Taper, explain why sine bar is Used for lesser values of on angle. **[6]**
 b) Explain difference between accuracy and precision. **[4]**

OR

- Q2)** a) Explain working, construction of a mechanical comparator,(Any one) What are its limitations. **[6]**
 b) Explain any one method of assessing the surface finish. **[4]**

- Q3)** a) How to check tooth thickness of a spur gear by using gear tooth vernier caliper. **[5]**
 b) Explain three wire method in thread measurement. **[5]**

OR

- Q4)** a) Explain Appraisal, Prevention, Failure costs with suitable examples. **[4]**
 b) Identify the given fit with sketch 25H7/g6, 25H7/p8 & 25H7/k10. **[6]**

- Q5)** a) Define quality control and give objectives of quality control. **[8]**
 b) State Seven Quality control tools. Explain any three in detail. **[8]**

OR

- Q6)** a) Write a short note on (any.2): **[8]**
 i) 5 S
 ii) TPM
 iii) Kaizen
 b) Explain ISO- 9001, 9002, 9003 & TS 16949 quality system standards. **[8]**

P.T.O.

- Q7) a)** Sheet metal components were inspected for wrinkle formations and following are the observations for number of defectives per sample lot of 100 numbers.

| | | | | | | | | | | | | | | | | | | | | |
|------------|---|---|---|---|---|---|---|----|---|----|----|----|----|----|----|----|----|----|----|----|
| Lot Number | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 |
| Defectives | 6 | 8 | 7 | 8 | 9 | 3 | 6 | 13 | 7 | 6 | 8 | 5 | 6 | 15 | 3 | 11 | 5 | 4 | 6 | 9 |

Determine the process is statistically stable or otherwise. If yes, suggest control limits for defectives. [6]

- b) Explain analysis of out of control condition referring control charts. [4]
 c) What are the advantages of sampling inspection over 100% inspection? Explain the difference between single sampling and double sampling plan. [8]

OR

- Q8) a)** A milling operation is required to generate a dimension 25 ± 0.5 mm. The observations over 450 components were summarized as follows

| | | | | | | | | | | | |
|------------|------|------|------|------|------|------|------|------|------|------|------|
| Dimensions | 25.7 | 25.9 | 25.0 | 25.8 | 25.6 | 25.7 | 25.5 | 25.4 | 25.3 | 25.2 | 25.1 |
| Components | 8 | 37 | 45 | 12 | 18 | 7 | 39 | 62 | 76 | 88 | 58 |

Determine the Average, Range, Standard Deviation and process capability. [8]

- b) Write note on FMECA and OC curve. [8]
 c) Explain process capability index. [2]

- Q9)** Write a short note on (any.4): [16]

- a) Affinity diagram
 b) Matrix diagram
 c) Kanban
 d) Process Decision Program Chart
 e) QFD
 f) JIT

