## T.E. (Mechanical) (Semester - II) Examination, 2011 METROLOGY AND QUALITY CONTROL (2008 Pattern)

Max. Marks: 100 Time: 3 Hours

Instructions: 1) Answer 3 questions from Section I and 3 questions from Section **II**.

2) Black figures to the right indicate full marks.

3) Use of Logarithmic Tables, Slide Rule, Mollier Charts, Electronic Pocket Calculator and Steam Tables is allowed.

4) Attempt any one question in each Unit.

5) Assume suitable data.

6) Answer to the Sections I and II should be written separately.

7) Answer 1 or 2, 3 or 4, 5 or 6, 7 or 8, 9 or 10, 11 or 12.

# SECTION - I Unit - 1

1. a) Differentiate between:

i) Systematic errors and Random error,

ii) Accuracy and Precision.

b) What is the difference between Alignment Test and Performance Test? Explain with neat sketches any four such tests on a Lathe machine.

### OR

2. a) Enumerate types of errors and sources of errors in dimension measurements and discuss Cosine and Parallax error with suitable example.

b) Differentiate between Mechanical and Pneumatic comparator. Explain with sketch the principle and working of Sigma Comparator.

#### Unit - 2

3. a) A shaft of 35  $\pm$  0.004 mm is to be checked by means of GO – NO GO gauge. Design the required dimensions for gauge. Draw the diagrammatic 10 representation.

b) Describe with neat sketch the optical arrangement of NPL Gauge Length Interferometer and explain how it is used to compute the thickness of slip gauge.

OR

P.T.O.

8

3

3

10

6

10



4.	a)	Design and make drawing of general purpose Go – NO GO Ring Gauge for inspection of a shaft of 30 f8. Given data with usual notations:						
		Tolerance unit = $i = 0.45 \sqrt{D} + 0.001 \text{ D}$ ,						
		Fundamental deviation for shaft 'f' = $-5.5D^{0.41}$ ,						
		The value of tolerance for IT8 = $25i$ , IT9 = $40i$ , Dia. Step = $18 - 30$ .						
	b)	Define terms: Primary and Secondary Textures and describe with neat sketch Taylor Hobson Surface Meter.	8					
		<b>Unit – 3</b>						
5.	a)	Show that the best wire size for measuring effective diameter of thread is given by $d = (p/2) \sec(\theta/2)$ . (where, $p = pitch$ of the thread).	6					
	b)	Sketch and describe a Gear Tooth Vernier Caliper.	4					
	c)	Write a short note on: Computer controlled Co-ordinate Measuring Machine.	6					
		OR						
6.	a)	Describe use of Devid Brown Tangent Comparator instrument for gear neasurement. Calculate the dimension of the Base Tangent Length over 5 teeth, when gear under inspection has following specifications: No. of teeth = 30, Module = 4, Pressure angle = 20, The shift of the tool in the gear to provide backlash = 0.03 mm.						
	b)	Discuss various types of pitch errors in screw threads.	4					
	c)	Explain use of Lasers in Metrology.	4					
		SECTION – II						
		<b>Unit – 4</b>						
7.	a)	Explain following Tools and techniques used for problem solving in quality circles.	12					
		1) Brain storming						
		2) Cause and effect diagram						
		3) Pareto analysis.						
	b)	Draw a neat sketch of House of quality and show various steps in QFD process.	4					
		OR						
8.	a)	Explain to make up the award criteria for Malcolm Balbrige national quality award.	5					
	b)	Explain basic elements of just in time.						
	c)	Explain Juran triology diagram.	5					

#### **Unit** - 5

- 9. a) Explain POKA-YOKE method developed by Shiego Shingo.
- 5

b) Explain purpose of Quality Audit.

- 5
- c) What are the implementation methodologies and limitations/difficulties in achieving ISO registration?

6

OR

- 10. a) Explain contribution of Demings fourteen point towards quality improvement. 6

b) Explain:

10

i) FMECA

ii) FTA

#### **Unit** – 6

11. a) Differentiate between single sampling, double sampling and sequential sampling plan.

9

b) Define following elements and show quality region on OC curve:

5

- 1)  $\alpha Risk$
- 2) B Risk
- 3) AOO
- c) Draw characteristics of OC curve.

4

OR

www.sppuonline.com

12. a) Calculate process capability and show the six-sigma and specified tolerance on normal distribution curve and comment specification of item  $500\pm5$ , n = 5, N = 20,  $A_2 = 0.58$ ,  $D_3 = 0$ ,  $D_4 = 2.11$ , (Use Table No. 1) Plot the chart and comment.

10

Table No. 1

Batch	1	2	3	4	5	6	7	8	9	10
$\overline{\mathbf{X}}$	501	498	500	503	501	500	497	502	503	496
R	3	4	2	4	3	5	4	2	6	4

b) Draw the flow chart for double sampling plan when N = 1500

4

 $n_1 = 100$ 

 $c_1 = 2$ 

 $n_2 = 50$   $c_2 = 4$ 

c) Calculate AOQ for single sampling plan N = 10,000, C = 1, P = 0.004. Pa = 0.558.